



# Surface casing corrosion Grane platform wells

Annette Pihl Pettersen, Equinor




## Agenda.

- Grane – Surface casing corrosion finding
- Immediate actions after finding
- Analyses
- Group task
- Key learning from Grane investigation
- Spinoffs




# Grane Platform

- Well design life 30 years
- Oldest wells: 24 years
- Youngest wells: 8 years
- 28" conductor 19.05mm wall thickness
- 18 5/8" surface casing 11,05 mm wall thickness



Grane location: 185 km west of Haugesund





Grane platform wells age profile



## Finding - Severe corrosion on surface casing on two wells

### During slot recovery

- Logged surface casing and found severe corrosion 0,5m below casing hanger
- The surface casing was cut and pulled 1 m below hanger on both wells
  - 16" surface casing and new 18 5/8" wellhead was run
- The location corresponded with liquid level in D annulus
- Correspondence with corrosion inside conductor/outside surface casing.
- The wells were 16 and 12 years at the time
- Actual lifetime of surface casing < design life





# Immediate actions performed on a representative number of wells (4 actions)

## 1. Logged upper 5 m of conductor with phased array



### • Result – worst case well

- Pitting: - WT reduced from 19mm to 4 mm.
- Overall cross-sectional corrosion: - Minor.

### Cause of corrosion

- Air vs liquid level
- Bacterial
- Inhibitive liquid vs non inhibitive liquid

Mapping of sectors/grid when logging with phased array



Pitting and cross sectional corrosion on worst case well



## Immediate actions performed on a representative number of wells


### 2. Tag TOC and determine liquid levels in D annuli

- Well A – TOC 73,5m liquid level 72,5m
- Well B – TOC 6,38m liquid level – At top
- Well C – TOC 23,5m liquid level 15m
- Well D – TOC 0,62m liquid level – At top.

### 3. Camera inspection of surface casing through D-annulus

- Limited access
- Algae growth
- Clouded liquid
- Hung up on cement patches

Camera inspections (pictures from 3 different wells)






# Immediate actions performed on a representative number of wells

## 4. Replace annulus liquid with inhibitive liquids.

- Replaced liquid in wells with access
- Top up in wells with limited or no access.

Set up for liquid replacement and top up





Analyses to map limits (performed on 2 worst case wells with regards to corrosion)

### **Total failure of both conductor and surface casing:**

Analysing independency in barriers, structural vs well integrity barriers.

- Result – Total failure of conductor and surface casing does not have an immediate effect of well barriers... BUT
- Result – Total failure of conductor and surface casing will lead to **wellhead drop of 1,4m on analysed well**

### **Strength and stability (conductor)**

- Result – Minimum required average circumferential wall thickness 9mm

### **Buckling – Result very dependant on cement in annuli. (conductor).**

- Result – Uncemented - Minimum required average circumferential wall thickness 15mm
- Result cemented - Minimum required average circumferential wall thickness 8,6mm



### **2 years BOP load (Fatigue on conductor)**

- Result – The margins to failure with current minimum thickness is considered robust.




# Group Task: Well 1 Oil producer with severely corroded surface casing WBS against reservoir

*What do you consider to be the main risks for this well with a severely corroded surface casing?*

Well 1 risks

Well 1 risks with degraded barrier

Any showstoppers or operational constraints?






# Group Task: Well 2 Oil producer with severely corroded surface casing WBS against reservoir

*What do you consider to be the main risks for this well with a severely corroded surface casing?*

Well 2 risks

Well 2 risks with degraded barrier


Any showstoppers or operational constraints?





## Key learning from Grane investigation

- Access in D annuli can be difficult
- Visual internal inspections (camera) can be challenging.
- Top of liquid level in annulus is a very important data point as this is most likely the worst spot for corrosion
- Liquid filled annulus can reduce corrosion rate (inhibitive liquid)
- Structural integrity of the conductor and surface casing will remain even with severe corrosion (On this field)
- Consequence of failed structural integrity with regards to well integrity should be investigated for all fields
  - Evaluation of potential drop of wellhead
  - Evaluation of independency of well barrier vs structural barrier





# Spinoffs

- **New department** to perform well lifetime assessments that ease learning and sharing across all Equinor licenses
- Updated **requirements** and **work process**
- Increased focus on **design documentation and updated analyses**
- Investigating **new technology** for better logging
  - Tool to screen out point of interest
  - Tool to have high accuracy and is less time consuming to use than phased array
- Closer cooperation with third party engineering companies to perform **analyses**.
- Tracking of **well components age** in iWIT (Equinor's well integrity management system)



## Spinoffs

- Better detail level and expanded **periodic maintenance programmes**:
  - Conductor inspection to include logging of internal corrosion – At least at main point of interests
  - Change out or top up D-annuli with inhibitive fluids (top up only if no access to change out)
    - Keep track of liquid level – Key point of interest for wall thickness measurements
- Establish a conductor **corrosion limit** on all platform fields
- **Logging** of surface casing whenever there is access.



© Equinor ASA

This presentation, including the contents and arrangement of the contents of each individual page or the collection of the pages, is owned by Equinor. Copyright to all material including, but not limited to, written material, photographs, drawings, images, tables and data remains the property of Equinor. All rights reserved. Any other use, reproduction, translation, adaption, arrangement, alteration, distribution or storage of this presentation, in whole or in part, without the prior written permission of Equinor is prohibited. The information contained in this presentation may not be accurate, up to date or applicable to the circumstances of any particular case, despite our efforts. Equinor cannot accept any liability for any inaccuracies or omissions.